# ALPHA UNIVERSE MULTI UNIT ABUTMENTS

## Healthier & Improved Aesthetics



ALPHA BIO TEC
Simplantology

Prosthetics

ALPHA UNIVERSE MULTI UNIT ABUTMENTS

Alpha-Bio Tec introduces a comprehensive screw-retained line for restorations on straight and tilted implants. The system provides stability, durability and high reliability while preserving the soft tissue and the bone. It is planned to facilitate the work of both the dentist and the technician.

The new AlphaUniverse Multi Unit system is intended for use in various clinical procedures in the maxilla and mandible, for partial or full edentulous restoration.

## FEATURES AND BENEFITS:

Following a meticulous research and development, Alpha-Bio Tec's new prosthetic parts are designed to simplify the work of the dentist. In addition, the system provides several key benefits:

### Easy handling

- one-piece abutments, straight and angled
- bendable metal holder for easier delivery




### Hard and soft tissue preservation

- concaved design promotes soft tissue healing and adaptation
- maintaining long term soft tissue stability
- a unique, narrower design makes the implant-abutment-soft tissues connection intact.




### Large variety of heights*

- six heights for straight abutments and three heights for angled abutments*
- two mostly used angles for tilted implants (17° and 30°)
- availability of restoration parts for both internal hex (IH) and conical hex (CHC) connections


* see ordering information on page 17



## Well proven, stable prosthetic platform

- long term durability
- a wide prosthetic cuff enables the use of thicker Porcelain crowns for stronger, more esthetic results
- low platform for limited intermaxilary space

| Low Platform | Wide Cuffs |
|---|---|
|  |  |

## Keeping the familiar prosthetic parts

- CAD/CAM restoration is available
- allowing the use of the existing, well-proven, restoration parts
- enabling to proceed with the same known workflow

| Scan Body | Ti-Base | Analog | Transfer |
|---|---|---|---|
|   |  |  |  |

## Prosthetic tools:

- **1.25mm drivers:**
  - new thin shaft design
  - purple colored for easy identification
- **1.5mm drivers:**
  - for straight abutment insertion

| 1.25mm Hex Driver | 1.5mm Manual Screw Driver |
|---|---|
|   |  |

# Multi Unit Restoration

**Multiple** Implant Restoration

For implants with up to 30° diversion between them

17° or 30° angled abutments for aligning the prosthetic platform when using tilted implants

**Single** Implant Restoration

For single unit screw-retained restorations

## Multiple Implants Restoration **Workflow***




Impression Taking


Model Forming and Prosthetics Simulation


Final Metal Frame Preparation


Final Restoration Placement

* The workflow is the same for both internal hex and conical hex connections. SPI implants were used in this models.

# STEP 1 Open Tray Impression **on Implant Level**

## A

CLINIC



Impression taking on implant level should be applied when there is an uncertainty about which abutment to use (straight, angled or which height). In these cases, the decision will be done by the doctor or technician after creating the casting model.

**Working steps for the physician**:

1. After ossoeintegration, place the transfers over the implants.
2. Connect the transfers manually to the implants with the 1.25mm driver.
3. Take an impression with materials of your choice, and send it to the laboratory.

**NOTE**: The implant analogs can be attached to the transfers by either the doctor or the lab technician.

### Parts & Tools

**Transfers**

| Open Tray | | Close Tray | |
|---|---|---|---|
| 5061 | 5070 (Screw) | 5060 | 5172 (Screw) |

**1.25mm Drivers**

| Manual Drivers | | Hex Drivers | | | Contra Angle |
|---|---|---|---|---|---|
| 4052 | 4053 | 4061 | 4055 | 4056 | 4165 |



## B

LAB

**Working steps for the technician**

1. Place and connect the appropriate implant analogs to the transfer.
2. Create a working model.
3. Choose the parts to be used for the specific case (heights and angulation).

**NOTE**: If a closed tray impression was taken, the implant should be attached to the transfer outside the impression tray and carefully inserted into its place.

### Parts & Tools

**Analog**

5080 (AI)

**Angled abuments**



| IH 17° | IH 30° | CHC 17° | CHC 30° |
|---|---|---|---|
| 5432 (1.5mm) | 5437 (1.5mm) | 7482 (1.5mm) | 7487 (1.5mm) |
| 5433 (2.5mm) | 5438 (2.5mm) | 7483 (2.5mm) | 7488 (2.5mm) |
| 5434 (3.5mm) | 5439 (3.5mm) | 7484 (3.5mm) | 7489 (3.5mm) |

**Straight abutments**

| IH Pro TCT-N | CHC Pro TCT-N |
|---|---|
| 5221 (0.75mm) | 5242 (0.75mm) |
| 5222 (1.5mm) | 5243 (1.5mm) |
| 5223 (2.5mm) | 5344 (2.5mm) |
| 5252 (3.5mm) | 5245 (3.5mm) |
| 5253 (4.5mm) | 5246 (4.5mm) |
| 5254 (5.5mm) | 5247 (5.5mm) |

# STEP 1 Open Tray Impression **on Abutment Level** (preferred)

## A

CLINIC



Before taking the impression, attach the abutments to the implants.

**NOTE:** It is advised to insert the 1.5mm angled abutment's screw **simultaneously** while connecting the abutment to the implant

For **classical impression** it is preferable to use the open tray transfer technique. The transfers may be connected in between rigidly by Resin or Acryl.

For **digital intraoral scanners** use scan bodies on top of the TCT platforms.

Dual use scan body
(5003)

| 30 Ncm | 30 Ncm | 20 Ncm | 20 Ncm | 30 Ncm | 30 Ncm |
|---|---|---|---|---|---|
| IH 17° | IH 30° | CHC 17° | CHC 30° | IH Pro TCT-N | CHC Pro TCT-N |

### Parts & Tools

**Angled abuments**

| IH 17° | IH 30° | CHC 17° | CHC 30° |
|---|---|---|---|
| 5432 (1.5mm) | 5437 (1.5mm) | 7482 (1.5mm) | 7487 (1.5mm) |
| 5433 (2.5mm) | 5438 (2.5mm) | 7483 (2.5mm) | 7488 (2.5mm) |
| 5434 (3.5mm) | 5439 (3.5mm) | 7484 (3.5mm) | 7489 (3.5mm) |

**Straight abutments**

| IH Pro TCT-N | CHC Pro TCT-N |
|---|---|
| 5221 (0.75mm) | 5242 (0.75mm) |
| 5222 (1.5mm) | 5243 (1.5mm) |
| 5223 (2.5mm) | 5344 (2.5mm) |
| 5252 (3.5mm) | 5245 (3.5mm) |
| 5253 (4.5mm) | 5246 (4.5mm) |
| 5254 (5.5mm) | 5247 (5.5mm) |

**Transfers**

| Open Tray | | | Close Tray |
|---|---|---|---|
| 5231 | 5248 | 6012 (Screw) | 5235 |

**1.25mm Drivers**

| Manual Drivers | | Hex Drivers | | | Contra Angle |
|---|---|---|---|---|---|
| 4052 | 4053 | 4061 | 4055 | 4056 | 4165 |

## B

LAB



### Parts & Tools

**Analog**

5211

**Classical method**

1. Place and connect the analogs manually to the transfers prior casting the model.
2. Create a working model.

**Digital intraoral methods**

1. Create a physical working model.

**OR**

2. Design the entire restoration digitally.

# STEP 2 Model Forming and Prosthetic Simulation

## A

LAB



A final layout of the bridge is designed and created for physicians check.
Can be formed in the materials of choice such as wax-up, resins or acrylics.

## B

CLINIC



The proposed design layout is checked by the physician to achieve the highest esthetic appearance and functionality.

# STEP 3 Final Metal Frame Formation and Check (Continued from abutment level)

## A

LAB

The framework is designed according to the approved layout (on steps 2A+B).

The technician should leave approximately 1.5mm for the ceramics.

For **classical restoration** the framework can be casted using casting sleeves.

For **digital restoration** the framework is done by milling or printing. In this case, various materials such as metals or Zirconia can be used. The framework can be connected directly to the abutments or through adhesive coping.

**NOTE**: The technician should work according to the STL libraries in his milling / printing machines.

### Parts & Tools

**Casting Sleeves**

5217 PST-N-AR △

5218 PST-N ○

**Screw Fixation**

6093 SFT-N

**1.25mm Drivers**

| Manual Drivers | | Hex Drivers | | | Contra Angle |
|---|---|---|---|---|---|
| 4052 1.25 | 4053 1.25 | 4061 1.25 L | 4055 1.25 | 4056 1.25 S | 4165 1.25 M |



**CAD\CAM Restoration**

5029 Adhesive Coping

5003 Scan Body

## B

CLINIC



The framework is checked for passive fit in patient's mouth.

### Parts & Tools

**Screw Fixation**

6092 SF-N

# STEP 4 Final Restoration

## A

LAB

The technician is finalizing the restoration with ceramics or materials of choice.

## B

CLINIC



The final restoration is placed in patient's mouth.

**Parts & Tools**

**Screw Fixation**

6092
SF-N

# Multi Unit Restoration

**Multiple** Implant Restoration

For implants with up to 30° diversion between them

17° or 30° angled abutments for aligning the prosthetic platform when using tilted implants

**Single** Implant Restoration

For single unit screw-retained restorations

# Single Implant Restoration **Workflow**


Oseointegrated Implant with Healing Abutment




Impression Taking*


Working Model Formation*


Checking Abutment Height


Casting Sleeve Placement


Metal Cast Check-up


Final Restoration Placament

* Stages 2-3 can be done based on digital intraoral methods using a scan body.

# Single Tooth Restoration - HBC Abutments System

The HBC Abutment system includes Ø4.7 mm abutment diameter with cuff heights of 0.5 ,1.5 or 2.5 mm
For best results please follow the work flow as followed:

## STEP 1 Oseointegrated Implant with Healing Abutment

CLINIC



Connect the appropriate healing abutment after implantation.

### Parts & Tools

**Healing Abutment**

**Ø 3.85 mm**
112 (3mm)
114 (4mm)
115 (5mm)

**Ø 5 mm**
124 (3mm)
125 (5mm)
**Ø 5.5 mm**
126 (3mm)
127 (5mm)

**Ø 4.6 mm**
116 (2mm)
109 (3mm)
117 (4mm)
110 (5mm)
118 (6mm)
119 (7mm)

**Ø 6 mm**
128 (3mm)
129 (5mm)
**Ø 7 mm**
130 (3mm)
131 (5mm)
**Ø 7.8 mm**
132 (3mm)
133 (5mm)

**1.25mm Drivers**

| Manual Drivers | | Hex Drivers | | | Contra Angle |
|---|---|---|---|---|---|



4052 4053 4061 4055 4056 4165

## STEP 2 Impression Taking

CLINIC




1. Select the transfer according to the working method of your choice – closed/open tray impression.
2. Place the transfer over the implant.
3. Connect the transfer to the implant manually.
4. Take an impression with materials of your choice and send it to the lab.

**NOTE:** For HBC the impression should be taken at the implant level.
The analog can be attached to the transfer by either the doctor or the lab technician.

### Parts & Tools

**HBC Transfers**

**Closed Tray Transfers**

5060 5170 5062

**Open Tray Transfers**



5061 5171 5070 5172

## STEP 3 Working Model Formation

LAB



Connect an analog to the transfer.

| NOTE: | Should a closed tray impression was taken, the abutment should be attached to the transfer outside the impression tray and carefully inserted into the implant. The transfer definite position should be verified. |
|---|---|

**Parts & Tools**

**Implant Analog**

5080
IA

## STEP 4 Checking Abutment Height (Optional)

CLINIC



1. Remove the healing cap.
2. Select the appropriate abutment.
3. Place the abutment manually over the implant for checking the gingival height. The abutment cuffs should be 0.5 to 1mm bellow the gingival height.

**Parts & Tools**

**HBC Abutments**

**Available Cuff Heights:**

6040
0.5mm

6041
1.5mm

6042
2.5mm

# STEP 5 Casting Sleeve Placement

LAB




**1.** Manually connect the casting sleeve with the appropriate LS screw, according to the HBC abutment height. Use the **1.25mm driver.**




**2.** Create the framework and cast it.

## Parts & Tools

### HBC Casting Sleeve

6070
PST-AR

**NOTE:** should be Anti-rotational

### LS Screws

| 6050 | 6051 | 6052 |
|---|---|---|
| 0.5mm | 1.5mm | 2.5mm |

**NOTE:** Other options include metal printing or milling. HBC Screws lengths are applicable to HBC heights.

# STEP 6 Metal Cast Check-up

CLINIC



1. Remove the healing abutment.
2. Check perfect passive fit between the metal cast and the abutment.
3. Send the metal cast to the lab with further instructions.
4. Re-connect the healing abutment.

**NOTE:** Other options include metal printing or milling.

### Parts & Tools

**HBC Abutments**

Available Cuff Heights:

6040 0.5mm | 6041 1.5mm | 6042 2.5mm

**LS Screws**

6050 0.5mm | 6051 1.5mm | 6052 2.5mm

# STEP 7 Final Restoration Placement

CLINIC




1. Remove the healing abutment.
2. Attach the final restoration to the implant with an LS screw with a 1.25mm driver.
3. Check the fittings to the soft tissue and the antagonist teeth (balance the occlusion if necessary).
4. Close with 30Ncm torque.

**NOTE:** Screw-retained restoration on a single implant can also be done with CoCr abutments. Please refer to the main catalog for ordering information.

### Parts & Tools

**LS Screw**

**Available Heights:**

6050 0.5mm | 6051 1.5mm | 6052 2.5mm

**1.25mm Drivers**

| Manual Drivers | Hex Drivers | | | Contra Angle | |
|---|---|---|---|---|---|



4052 1.25 | 4053 1.25 | 4061 1.25 L | 4055 1.25 | 4056 1.25 S | 4165 1.25 M

# ORDERING INFORMATION

# Insertion Tools

## Hex Driver 1.25 mm (Stainless Steel)

| | Manual Screw Driver | Short Manual Screw Driver | Long Hex Driver | Hex Driver | Short Hex Driver | Contra Angle Motor Mount |
|---|---|---|---|---|---|---|
| Code | HHS 1.25 | HHSS 1.25 | HTD 1.25L | HTD 1.25 | HTD 1.25 S | HT 1.25M |
| Ref. No. | 4052 | 4053 | 4061 | 4055 | 4056 | 4165 |




## Hex Driver 1.5 mm (Stainless Steel)

| | Manual Hex Driver | Long Manual Hex Driver | Hex Driver | Short Hex Driver | Motor Mount Hex Driver |
|---|---|---|---|---|---|
| Code | HHS 1.5 | HHL 1.5 | HTD 1.5 | HTD 1.5S | HT 1.5 |
| Ref. No. | 4059 | 4060 | 4057 | 4058 | 4168 |



# Pro TCT-N Straight Abutments – For restoration up to 30°




## Pro TCT-N Abutment System (Internal Hex)

| | | | | | | |
|---|---|---|---|---|---|---|
| Dimensions | A: Ø4.7 mm<br>B: 0.75 mm<br>C: 1 mm | A: Ø4.7 mm<br>B: 1.6 mm<br>C: 2.8 mm | A: Ø4.7 mm<br>B: 2.6 mm<br>C: 3.8 mm | A: Ø4.7 mm<br>B: 3.6 mm<br>C: 4.8 mm | A: Ø4.7 mm<br>B: 4.6 mm<br>C: 5.8 mm | A: Ø4.7 mm<br>B: 5.6 mm<br>C: 6.8 mm |
| Code | TCT0.5-N | TCT1.5-N | TCT2.5-N | TCT3.5-N | TCT4.5-N | TCT5.5-N |
| Ref. No. | 5221 | 5222 | 5223 | 5252 | 5253 | 5254 |




## TCT-N CHC (Conical Hex)

| | | | | | | |
|---|---|---|---|---|---|---|
| Dimensions | A: Ø 4.7 mm<br>B: 0.75 mm<br>C: 1.95 mm | A: Ø 4.7 mm<br>B: 1.5 mm<br>C: 2.7 mm | A: Ø 4.7 mm<br>B: 2.5 mm<br>C: 3.7 mm | A: Ø 4.7 mm<br>B: 3.5 mm<br>C: 4.7 mm | A: Ø 4.7 mm<br>B: 4.5 mm<br>C: 5.7 mm | A: Ø 4.7 mm<br>B: 5.5 mm<br>C: 6.7 mm |
| Code | TCT- N 0.75 CHC | TCT-N 1.5 CHC | TCT-N 2.5 CHC | TCT-N 3.5 CHC | TCT-N 4.5 CHC | TCT-N 5.5 CHC |
| Ref. No. | 5242 | 5243 | 5244 | 5245 | 5246 | 5247 |

# Angled Abutments




## Angled Abutments (Internal Hex)



| | | | | | | |
|---|---|---|---|---|---|---|
| Degree | | 17° | | | 30° | |
| Dimensions | A: Ø 4.7<br>B: 1.5 mm | A: Ø 4.7<br>B: 2.5 mm | A: Ø 4.7<br>B: 3.5 mm | A: Ø 4.7<br>B: 1.5 mm | A: Ø 4.7<br>B: 2.5 mm | A: Ø 4.7<br>B: 3.5 mm |
| Code | AU 17-1.5 IH | AU 17-2.5 IH | AU 17-3.5 IH | AU 30-1.5 IH | AU 30-2.5 IH | AU 30-3.5 IH |
| Ref. No. | 5432 | 5433 | 5434 | 5437 | 5438 | 5439 |




## Angled Abutments (Conical Hex)



| | | | | | | |
|---|---|---|---|---|---|---|
| Degree | | 17° | | | 30° | |
| Dimensions | A: Ø 4.7<br>B: 1.5 mm | A: Ø 4.7<br>B: 2.5 mm | A: Ø 4.7<br>B: 3.5 mm | A: Ø 4.7<br>B: 1.5 mm | A: Ø 4.7<br>B: 2.5 mm | A: Ø 4.7<br>B: 3.5 mm |
| Code | AU 17-1.5 CHC | AU 17-2.5 CHC | AU 17-3.5 CHC | AU 30-1.5 CHC | AU 30-2.5 CHC | AU 30-3.5 CHC |
| Ref. No. | 7482 | 7483 | 7484 | 7487 | 7488 | 7489 |

# Impression Taking and Healing Abutments

| | Pro Healing Abutments | | | Open Tray Transfer | | | Closed Tray Transfer |
|---|---|---|---|---|---|---|---|
| |  |  |  |  |  |  |  |
| Height | 4 mm | 6 mm | 4 mm | 10 mm | 10 mm | 13 mm | 8.5 mm |
| Code | HCT4-N | HCT6-N | HCTB-N | TST-N | TCT-N-R | SFL-N | TS-N |
| Ref. No. | 5236 | 5237 | 5241* | 5231 | 5248 | 6012 | 5235 |
| Instructions | Recommended closing torque: 10 Ncm. Use screw 6092. | | | Close manually | | | Close manually |

| | Analog | Temporary Abutment | Screw Fixation | | Burnout Sleeve | |
|---|---|---|---|---|---|---|
| |  |  |  | Laboratory  |  |  |
| Material | Titanium | Titanium | Titanium | Titanium with coating | Plastic | Plastic |
| Code | BTT-N 5211 | TTA-N | SF-N | SFT-N | PST-N-AR | PST-N Non-Engaging |
| Ref. No. | | 5216 | 6092 | 6093 | 5217 | 5218 |
| Instructions | | Recommended closing torque: 25 Ncm. Use screw 6092. | Use HTD 1.25 mm for insertion. Recommended closing torque for the final restoration on straight abutments: 25 Ncm. | | Recommended closing manually only (without tool). Use screw 6093. | |

# HBC Abutment System

| | HBC Abutment | | | | Screws for HBC abutments | | | Burnout Sleeve |
|---|---|---|---|---|---|---|---|---|
| |  |  |  |  | |  |  |  |  |
| Dimensions | A: Ø4.7 mm B: 0.5mm C: 2.6mm | A: Ø4.7 mm B: 1.5mm C: 3.6mm | A: Ø4.7 mm B: 2.5mm C: 4.6mm | | Use With | HBC 0.5 | HBC 1.5 | HBC 2.5 | |
| Code | HBC 0.5 | HBC 1.5 | HBC 2.5 | | Code | LS O.5 | LS 1.5 | LS 2.5 | PST-AR |
| Ref. No. | 6040 | 6041 | 6042 | | Ref. No. | 6050 | 6051 | 6052 | 6070 |

# CAD/CAM Restoration

| | Adhesive Copings | | Dual Use Scan Body | Screw |
|---|---|---|---|---|
| | Engaged | Non Engaged | | |
| |  |  |  |  |
| Code | TAC-TCT-N | TAC-TCT-N-R | IOSB-TCT-N | S-DM-SR |
| Ref. No. | 5028 | 5029 | 5003 | 4994 |
| Instructions | For single tooth | For bar/bridge | For lab use and intra-oral | For direct mounting |

# Impression Taking

| | Closed Tray Transfer | | | |
|---|---|---|---|---|
| | Standard | | Slim | Screw |
| |  |  |  |  |
| Code | HLT | HLTS | HLTLS | SHLT |
| Ref. No. | 5060 | 5170 | 5062 | 5172 |

**Note:** each transfer is supplied with its corresponding screw.

| | Open Tray Transfer | | | |
|---|---|---|---|---|
| |  |  |  |  |
| Code | HLTO | HLTOS | LGP | SHLT |
| Ref. No. | 5061 | 5171 | 5070 | 5172 |

**Note:** each transfer is supplied with its corresponding screw.

Simplantology,
In Everything We Do!

**Authorized European regulatory representative:**
EC REP **MEDES LIMITED**
5 Beaumont Gate, Shenley Hill
Radlett, Herts WD7 7AR, England, U.K
Tel/Fax: +44 1923859810

**www.alpha-bio.net**

AlphaBio TEC
Simplantology